

CORRECTION OF SERVICE MANUAL

Date: June 17, 2004 No.: SCH04007 (1/1)

MODEL No.
XV-HTD520/KUCXJ

S/M No.
RRV2606

PG
16,24


MODEL No.
XV-HTD50/MYXJ

S/M No.
RRV2634

PG
16,24

Please correct your service manual


Please refer to RRV2606 page 16 and RRV2634 page 16.



XYW3004
(correct)

Please refer to RRV2606 page 24 and RRV2634 page 24.

2/3 DVDM ASSY (XWX3034)



XYW3004
(correct)

PIONEER SERVICE NETWORK CORPORATION

K.NOHARA ,MANAGER
HE

Technical Support Group
Service Support Division

Memo: SPC59-129 YI,61
SPC0406-1

